
Preliminary Measurements of RFA Prototype and Beam Measurements


C.Y. Tan 23 Dec 2008

Argonne RFA






FNAL RFA



Setup



Pulse Generator


Pulse generator can output up to 10Vp pulses. However, due to the matching network on the wire, I only have 600mVp on the wire.

In order to get a good signal, I have to the wire as close as possible to the RFA. The bottom of the RFA is about 1/2" to the wire.


Important Discovery

The connecting wires are acting as antennas because I can change the size of the signal on the cathode by rotating it w.r.t. slot direction.

I need to look more carefully into this.




Without slots



Image

Add Slots



Assign Save to


Image

File Utilities


15 Dec 2008 13:15:14

Real Beam

Signal on MI RFA. Looks like NOISE




Fourier transforming the grid signal



More details in rfa.pdf

Zoomed in



Conclusion

- I need to make a few more measurements on real beam: I want to see the 10kHz line.
- Measure with ANL RFA on test bench.
- Orientate the wires w.r.t. slots and try shielded cable.
- I think I know what is needed for the electronics.
 - We have the rad hard parts
 - I need \$20 rad hard transistors.
 - Simulate and build!